## General Environmental Incident Summary

Incident: 3579 Date/Time Notice: 12/11/2014 0823 DEM Incident No: 3492

Responsible Party: American Crystal Sugar Company

Date Incident: 12/10/2014 Time Incident: 1230 Duration: 10 minutes

County: Pembina Twp: 159 Rng: 51 Sec: 14 Qtr: Lat: 48.58855 Long: -97.17744 Method: Interpolation from map

Location Description: American Crystal Sugar Company

8152 County Highway 44 North, Drayton, ND

58225-0190

Submitted By: Paul King Affiliation: ECS

Address: 8152 County Highway 44

City: Drayton State: ND Zip:

Received By:

Contact Person: Paul King

8152 County Highway 44 Drayton, ND 58225-0190

Distance Nearest Occupied Building: 2 Miles Release Contained: Yes

Type of Incident: Tank Leak

Description of Released Contaminant: Sugar Beet Molasses

Volume Spilled: 750.00 gallons Ag Related: No

EPA Extremely Hazardous Substance: No Reported to NRC: Unknown

Cause of Incident:

Empting tank for cleaning. While attempting to remove remaining liquid molasses back pressure on suction line caused additional molasses to enter tank and was accidentally released through inspection/access hatch.

Risk Evaluation:

None

# of Fatalities: 0 # of Injuries: 0 Affected Medium: 03 - soil

Potential Environmental Impacts:

None

## Action Taken or Planned:

Checking the position of all valves prior to finial graining of tanks will be added to the tank emptying pre-cleaning SOP. Majority of molasses was drained into the factory wastewater system. Remaining molasses was absorbed using dried sugar beet pulp.

Wastes Disposal Location: Molasses saturated beet pulp will be blended with beet tailings and provided to livestock feeders.

Agencies Involved:

## **Updates**

Date: 12/11/2014 Status: Reviewed - Assigned to NDDoH Division Author: Roberts, Kris

**Updated Volume:** 

Notes:

Referred to Water Quality Division for any needed followup.

Date: 12/29/2014 Status: Reviewed - No Action Required Author: Haroldson, Marty

**Updated Volume:** 

## Notes:

Visited with Steve Lindquist, plant chemist, and confirmed that the molasses was cleaned up and handled in accordance with the statements in the initial incident report.